



Our retail price is a recommendation only. Prices in offer may differ. All prices indicated 0,00 € will follow in the offer.



RATIOPARTS REPLACEMENT CHAIN RAIL LENGTH 38 CM DRIVE LINK THICKNESS 1.5 MM 65-PC.

SKU: 4023055555017

Replacement chain rail length 38 cm drive link thickness 1.5 mm 65-pc.

Categories: [Gardening and landscaping](#), [Petrol power saws and accessories](#)

Product Features: Length of rail: 38 cm
Chain pitch: 0.325
Suitable for: HUSQVARNA 445, 445e, 450, 450e, 455(e) Rancher, 455(e) II Rancher, 460 Rancher, 543 XP, 500 XP II, 545 II
Brand: RATIOPARTS

Scope of delivery:
1,00 ST Replacement chain rail length 38 cm drive link thickness 1.5 mm 65-pc. |

PRODUCT DESCRIPTION

Professional saw chain

- Half-chisel chain with rounded cutting teeth
- Without safety link, for a higher cutting capacity
- Please note the manufacturer's assembly and safety instructions Further technical information:
- Number of drive links: 65Pc.
- Drive link strength: 1.5mm

PRODUCT DATASHEET LEGAL NOTE

Please note that the information on this datasheet is provided without warranty and is intended only as non-binding information about the product. Any liability for damages or losses that may arise from the use of this information is excluded. We therefore recommend that you verify the information on this datasheet with other sources before making any decisions based on this information. Additional information about the product can be found on our website.