



Our retail price is a recommendation only. Prices in offer may differ. All prices indicated 0,00 € will follow in the offer.



## RATIOPARTS REPLACEMENT CHAIN RAIL LENGTH 40 CM DRIVE LINK THICKNESS 1.5 MM 60-PC.

**SKU:** 4023055558933

Replacement chain rail length 40 cm drive  
link thickness 1.5 mm 60-pc.

---

**Categories:** [Gardening and landscaping,](#)  
[Petrol power saws and accessories](#)

**Product Features:** Length of rail: 40 cm  
Chain pitch: 3/8  
Suitable for: HUSQVARNA 455 Rancher, 455E  
Rancher, 455 II Rancher, 455e II Rancher, 460  
Rancher, 560 XP, 555, 562 XP, 572 XP, 565,  
390 XP, 395 XP  
Brand: RATI

Scope of delivery:  
1,00 ST Replacement chain rail length 40 cm  
drive link thickness 1.5 mm 60-pc. |

## PRODUCT DESCRIPTION

Professional saw chain

- Half-chisel chain with rounded cutting teeth
- Without safety link, for a higher cutting capacity
- Please note the manufacturer's assembly and safety instructions Further technical information:
- Number of drive links: 60Pc.
- Drive link strength: 1.5mm

## PRODUCT DATASHEET LEGAL NOTE

Please note that the information on this datasheet is provided without warranty and is intended only as non-binding information about the product. Any liability for damages or losses that may arise from the use of this information is excluded. We therefore recommend that you verify the information on this datasheet with other sources before making any decisions based on this information. Additional information about the product can be found on our website.